
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>1</u> of <u>3</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/22/08
Test to be Performed:	Ground Condition:	Supervisor: RT
Smoke: _X Dyed Water:	Dry:X	
Manhole ID: S23II 038	Test ID: 0994-641	Notifications Made: x (Residents, Fire, 311)

**Field Sketch:** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 3			
Sewershed: Jones Falls			Company: Savin Engineers				Date: 7/22/08		
Test to be Performed:			Ground Condition:				Supervisor: RT		
Smoke	e: X Dye	d Water:	_	Dry: _^	Dam	p: We			
Manhole ID: S23 II 038		Test ID: 0994-641				Notifications Made:X (Residents, Fire, 311)			
<b>Field Sketch:</b> (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)									
Defect				Source			Drainage		Photo
No.		Address		Туре	Location	Sector	Area	Severity	Number
	522 Sanford Pla	ace		03	08	02	10	03	OB01-01
	2304 Pennsylva			12	02	02	1000	04	OB02-01
	20011 0111109111	411147170			<u> </u>	V2	1000	0.	020201
				<del> </del>					
				<del> </del>					
				-					
				OBSER\	/ATION	CODES			
	Source Type	Location	Sector		I		Location		
04			Public	Severity	40	Source Type			
	Main Sewer	Paved Concrete		No Smoke		MH Frame Seal Storm Drain	Non-Paved		
	Service Line	Paved Asphalt	Private	Trace			Field/Woods		
	Cleanout	Paved Other		Moderate		Catch Basin/Inlet			
	Downspout	Driveway		Major		Storm Manhole	Golf Course		
	Area Drain	Sidewalk				Storm Ditch	Other		
	Driveway Drain	Curb		ļ		Excavation			
	Stairwell Drain	Yard- Front		-	16	Other			
	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side	ĺ		ĺ		1		

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>3</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/22/08
Test to be Performed:	Ground Condition:	Supervisor: RT
Smoke: _X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S23II 038	Test ID: 0994-641	Notifications Made: x (Residents, Fire, 311)

**Field Sketch:** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



0994-641\_OB01-01



0994-641\_OB02-01